





Fitting Point
Prism Reference Point

Ink Marking: Blue
Invisible Marking: Red

Material	Invisible Marking
Hard Resin 1.5	FF SV-CR
Transitions V 1.5	FF SV-TR
Polarized 1.5	FF SV-PZ
Drivewear® Activated by Transitions® 1.5	FF SV-DW
Polycarbonate 1.59	FF SV-PC
Polycarbonate 1.59 Transitions V	FF SV-PT
Polycarbonate 1.59 Polarized	FF SV-PPZ
SuperLite™ 1.6	FF SV-16
SuperLite 1.6 Transitions V	FF SV-T6
SuperLite 1.67	FF SV-67
SuperLite 1.67 Transitions V	FF SV-T67
SuperLite 1.74	FF SV-74